Shell Exploration and Production Company (SEPCo)

Lifted Equipment Certification Form

Shell Purchased: Sup	plier:	
Rental Equipment: Owr	ner (Vendor):	
Tare Weight (lbs.): 2,90 (Empty weight of container, tank, pace	o:kage, skid)	
Working Load Limit (lbs.): (Weight of liquid in tank, items in conf		
Maximum Gross Weight (lbs.) (Tare Weight + Working Load Limit =	Max. Gross Weight)	
Floor Area Loading (psf):(Allowable floor area loading for conta	ainers or buildings)	PBX-1 PBX-2
Unique Identification Number (For rental equipment only)	FOR 4 SERIAL UNITS:	PBX-3 PBX-4
DESIGN NO. NT033		
I certify that the above-described lidynamic lifting in accordance with edition) and SEPCo Document OPS	the provisions of API RP2A (I	or offshore atest
Low Rus a	P.E. 91	25 3 Date
Registered Professional Engineer	(Civil or Structural)	Date
CANTINE SINGLE S	Notes: 1. Owners of rental equipment of this form on file for duratic and shall submit a copy to S 2. ISO blocks/connectors are nused as lifting attachment po	on of equipment lith thelt upon request not permitted to be

Seal